

Please note some of these devices are still under development and currently unavailable. Please phone for specific advice.

Motorola Tk30 Steering Wheel Integration

Audi -----	A2 -----	2004>	Mercedes ----	A (W169) -----	2004>
	A3 -----	2002>		B (W245)-----	2005>
	A4 -----	2001>		C (W203)-----	2000*>
				CLK (W209) –	2003>
BMW -----	1 (E81) -----	2004>		E (W211)-----	2003>
	3 (E46) -----	1998>		SLK (R171) —	2004>
	5 (E39) -----	1996>			
	6 (E63) -----	2004>	VW -----	Eos -----	2006>
	7 (E38) -----	1995*>		Golf V -----	2003>
	X3 (E83) -----	2003>		Passat -----	2005>
	X5 (E53) -----	2002>		Tiguan -----	2007>
	Z4 (E85) -----	2002>			

Motorola Tk30 Steering Wheel & Display Integration

Audi -----	A2 -----	2004>	Renault -----	Clio -----	2005>
	A3 -----	2002>		Laguna -----	2005>
	A4 -----	2001>		Megane II ----	2005>
				Megane III ----	2008*>
Citroen -----	C2 -----	2006>		Modus -----	2005>
	C3 -----	2006>		Scenic -----	2005>
	C4 -----	2006>		Twingo -----	2007>
	C5 -----	2005>			
	C8 -----	2006>	Vauxhall -----	Agila -----	2004>
Mercedes ----	A (W169) -----	2004>		Antara -----	2006>
	B (W245)-----	2005>		Astra -----	2004>
	C (W203)-----	2000*>		Corsa -----	2005>
	CLK (W209) –	2003>		Signum -----	2004>
	E (W211)-----	2003>		Tigra -----	2005>
	SLK (R171) —	2004>		Vectra -----	2004>
Peugeot -----	207 -----	2006>	VW -----	Eos -----	2006>
	307 -----	2005>		Golf V -----	2003>
	308 -----	2007>		Passat -----	2005>
	407 -----	2005>		Tiguan -----	2007>
	807 -----	2005>			